

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

JX1380
North
> 1
1.742 mi.
9198 ft.

MANHOLE 38207
KINGS HIGHWAY & W 8TH ST
BROOKLYN, NY

NY Spills S103484867
N/A

Site 2 of 2 in cluster JX

Relative:
Higher

Actual:
19 ft.

SPILLS:

Name: MANHOLE 38207
Address: KINGS HIGHWAY & W 8TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9808028 / 2002-12-30
Facility ID: 9808028
Facility Type: ER
DER Facility ID: 172963
Site ID: 208453
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1998-09-30
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1998-09-30
CID: 365
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-09-30
Spill Record Last Update: 2002-12-30

Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: Not reported
Contact Name: RICHARD ROACH
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT Con Ed e2mis #120179: 9/30/98 1330HRS--SACCOMAGNO REPORTS
FOUND UNDIAPERBLE SHEEN IN MH-38207 CONTAINED NO SEWERS OR WATERWAYS
AFFECTED SAMPLE TAKEN TAG#12197 PLACED. LAB RESULT RECEIVED 10/1/98 -
1305. 98-10335. <1.0 PPM. 10-7-98 1600 HRS K.QUEST FLUSH REPORTS IN
MH38207 CLEANUP COMPLETED AND E.S.TAG #12197 WAS REMOVED. < 1PPM"

Remarks: "SPILL OF 1 OUNCE OF UNK PETROLEUM CONTAINED IN THE MANHOLE"

All Materials:

Site ID: 208453
Operable Unit ID: 1065590
Operable Unit: 01
Material ID: 315563
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Oxygenate:

Not reported